



NewPro Long-term coating RK CCS with Plexiglass Ticket Machine Ludwigshafen-Mannheim



Graffiti smearing with 2-component lacquers and underbody protection

Test object

Ticket machine surface treated with **NewPro Long-term coating RK CCS**

Graffiti smearing with 2-component lacquers and underbody protection



zum Vergleich unbeschmierte Seite

Compare:

left side treated with **NewPro RK CCS**, no graffiti

Enlarged Picture




Graffiti (2-K-Lacke und Unterbodenschutz)



Zwischenstand:
 Nach ca. 10 Minuten Reinigungsaufwand dieser Zustand erreicht.

Interim cleaning status after approx. 10 minutes cleaning effort



Final evaluation after approx. 20 minutes cleaning
Bottom line:
 „as if nothing ever happened“

Final evaluation after approx. 20 minutes cleaning

Example 2:

another ticket machine. Treated with NewPro Long-term coating RK CCS



Treated with NewPro Long-term coating RK CCS